

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
KEY LESSONS LEARNED FROM ISSUES RESOLVED AND BEST PRACTICES
In 3rd Quarter 2026

Program/Project Title	Location	Implementing Agency	Problem/ Issue		Strategies/Actions Taken to Resolve the Problem/Issue	Responsible Entity/Key Actors and their Specific Assistance	Lessons learned and Good Practices that could be shared to the NPMC/Other PMCs
			Nature	Details			
Construction/Concreting of Access Road to Demo Farm in Brgy. Lapgap	Brgy. Lapgap, Maydolong, Eastern Samar	LGU-Maydolong	None	None			
Construction of Riverwall in Brgy. San Gabriel	Brgy. San Gabriel, Maydolong, Eastern Samar	LGU-Maydolong	Quakity of finished project	It was noted that the riverwall did not have a smooth finish. Visible animal footprints were present on portions of the structure, and some sections of the wall had already begun to show signs of peeling.	Inform the contractor on the findings.	Constructor - to properly smoothen the finishing of the wall	Formulate a Construction Compliance and Project Impact Monitoring Toolkit

Submitted by:
 Designation/Office:
 Date:


RAYNITA A. ABOY
 MPDC/LPMC Secretariat
 October 01, 2026

Approved by:
 Date:


ELIA A. MELENDRES
 Punong Barangay/LPMC President
 October 01, 2026

Noted by:
 Date:


ATTY. LOUIE A. BORJA
 Municipal Mayor