

**LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
FOR CY 2026**

LPMC: ALBUERA

Description of Indicators	Baseline Data (2025)	Target Values (2026)				Sources of Data	Method of Collection	Timing/Frequency	Unit/Person Responsible to Collect	Unit/Person Responsible to Report
		First Quarter	Second Quarter	Third Quarter	Fourth Quarter					
1. Improvement of Super Health Center	Newly-constructed Super Health Center		Super Health Center improved			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
2. Landscaping of Super RHU and Multipurpose Building Premises at Brgy. San Pedro	Newly-constructed Super Health Center		Super Health Center improved			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
3. Concreting of Multipurpose Building Parking Space at Brgy. San Pedro	Earth-and-Gravel Parking Space		Multipurpose Building Parking Space concreted			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
4. Concreting of Super RHU Building Parking Space at Brgy. San Pedro	Earth-and-Gravel Parking Space		Super RHU Building Parking Space concreted			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
5. Improvement of Market Buildings	Existing Market Building		Market Buildings improved			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
6. Construction of wet market building	Existing Wet Market Building			Wet Market Building constructed		Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
7. Construction of Swimming Pool (Olympic Size) at SMR	Existing Resort Swimming Pool			Olympic Size Swimming Pool constructed		Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
8. Improvement of Multipurpose building (Balugo)	Existing Multipurpose Building		Multipurpose Building improved			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
9. Installation of Street Lights (Benolho)	Existing Street Lights		Additional Street Lights installed			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
10. Construction of Flood Control Dike (Cambalading)	No Existing Flood Control Dike			Flood Control Dike constructed		Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson

11. Construction of Retaining Wall with Embankment (Damula-an)	Existing Drainage Canal			Retaining Wall with Embankment constructed		Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
12. Rehabilitation/Improvement of Multipurpose Building (Doña Maria)	Existing Multipurpose Building			Multipurpose Building rehabilitated/improved		Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
13. Concreting of Barangay Road (Mahayahay)	Existing Barangay Road		Additional Barangay Road concreted			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
14. Concreting of Barangay Road (Poblacion)	Existing Barangay Road		Additional Barangay Road concreted			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
15. Rehabilitation/Improvement of Evacuation Center (Salvacion)	Existing Evacuation Center		Evacuation Center rehabilitated/improved			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
16. Improvement of Multipurpose Building (San Pedro)	Existing Multipurpose Building			Multipurpose Building improved		Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
17. Concreting of Barangay Road (Seguinon)	Existing Barangay Road		Additional Barangay Road concreted			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
18. Construction of Perimeter Fence (Tabgas)	Existing Perimeter Fence		Additional Perimeter Fence constructed			Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
19. Improvement of Multipurpose Building (Talisayan)	Existing Multipurpose Building			Multipurpose Building improved		Site Inspection Progress from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson

Prepared by:

Engr. KARLA A. GENCIANOS, EnP
MPDC

Noted by:


ROLAN E. ESPINOSA
LPMC Chairperson

Approved by:


ROLAN E. ESPINOSA
Municipal Mayor