

LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
For CY 2026

PMC: Carigara, Leyte


Description of Indicators	Baseline Data (Y2025)	Target Values (2026)				Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/ Person Responsible to Collect	Unit/ Person Responsible to Report
		1st Quarter	2nd Quarter	3rd Quarter	4th Quarter					
Financial Assistance/ Counterpart to Barangay for Construction of Riprap - Brgy. Guindapunan East	Lack of Riprap leads to possible coastal erosion	Constructed and functional Riprap				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Road Concreting in Sitio Tangpi - Brgy. Binibihan	Unpaved road	Concreted road				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Road Opening - Brgy. Cogon	No through road causing inaccessibility.	Concreted and fully functional and accessible road				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Road Reblocking - Brgy. Hiluctogan	Damaged or defective road	Repaired and functional road				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Road Concreting - Brgy. San Juan	Unpaved road	Concreted road				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members

Financial Assistance/Counterpart to Barangay for Road Reblocking Concreting-Brgy. Paglaum	Damaged or defective pavement	Repaired and functional road				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Road Concreting - Brgy. Tigbao	Unpaved road	Concreted road				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for the Installation of Solar Street Lights - Brgy. Upper Sogod	Existing streetlights are not disaster-resilient	Installed disaster-resilient streetlights				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Improvement of Multipurpose Pavement-Brgy. Tangnan	Existing structure needs renovation	Improved and safe Multipurpose Pavement				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Construction of Drainage Canal-Brgy. Barugohay Norte	Incidence of flooding resulting to risk in damage to property and potential health hazard	Constructed and functional drainage canal				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members

Financial Assistance/Counterpart to Barangay for Improvement of Multi-Purpose Pavement (Construction of Fence)-Brgy. Tagak	Absence of Fence in the Multipurpose Pavement	Constructed fence around Multipurpose Pavement				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Concrete Pathway- Brgy. Bislig	Unpaved pathway	Concreted pathway				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Financial Assistance/Counterpart to Barangay for Road Concreting- Brgy. Upper Hiraan	Unpaved road	Concreted road				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Concreting of Multi-Purpose Pavement - Brgy. Sawang, Carigara, Leyte	Unpaved pavement	Concreted and safe Multipurpose Pavement				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Repair of Fish Shed House (Phase 1) - Brgy. Baybay, Carigara, Leyte	Existing Fish Shed house shows damage due to general wear and tear from weather	Repaired and functional Fish Shed House	Improved and safe Kan Gara Gymnasium			MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Construction of Food Park and Food Stalls along Boulevard Phase 2 - Along Boulevard, Carigara, Leyte	Existing structure not yet fully complete	Fully complete and constructed Food Park and Food Stalls				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members

Construction of Fence at Municipal Dumpsite - Brgy. Parag-um, Carlgara, Leyte	Absence of fence at the Municipal Dumpsite				Constructed fence	MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Construction of Market Stalls in Public Market - Brgy. Baybay, Carigara, Leyte	Not yet fully constructed and completed				Established market stalls in public market	MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Rehabilitation and Improvement of Drainage Canal - Aguja St., Brgy. Ponong, Carigara, Leyte	Non-functional existing drainage canal		Restored and improved drainage canal			MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members
Repair of Market Office - Brgy. Baybay, Carigara, Leyte	Existing Market Office is dilapidated	Fully functional and safe Market Office				MEO	Inspection Report	One Shot (<i>more than once as needed</i>)	LPMC Secretariat	LPMC members


Prepared by:



EnP DARYL DANIEL G. BODO

PMC Secretariat

Approved:



Hon. RANIEL A. MARQUEZ

PMC Chairperson

Noted by:



Hon. EDUARDO T. ONG, JR.

LCE