


**LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
For CY 2026**


PMC: MERIDA, LEYTE

Description of Indicators	Baseline Data (Y0)	Target Values (2026)				Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/ Person Responsible to Collect	Unit/ Person Responsible to Report
		1st Quarter	2nd Quarter	3rd Quarter	4th Quarter					
Output per project: Title: Construction of Core Local Road at Brgy. Calunasan, Merida, Leyte Output: 88.00m Length Concreting	0 linear meter PCCP, Existing Earth Road		88 l.m. PCCP Constructed			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Construction of Core Local Road at Brgy. Canbantug, Merida, Leyte Output: 160.00m Length Concreting	0 linear meter PCCP, Existing Earth Road		160 l.m. PCCP Constructed			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Construction of Core Local Road at Brgy. Libjo, Merida, Leyte Output: 105.00m Length Concreting	0 linear meter PCCP, Existing Earth Road		105 l.m. PCCP Constructed			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Construction of Core Local Road at Brgy. Puerto Bello, Merida, Leyte Output: 210.00m Length Concreting	0 linear meter PCCP, Existing Earth Road		210 l.m. PCCP Constructed			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Construction of Core Local Road at Brgy. San Jose, Merida, Leyte Output: 120.00m Length Concreting	0 linear meter PCCP, Existing Earth Road		120 l.m. PCCP Constructed			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Construction of Multi-Purpose Building at Brgy. San Isidro, Merida, Leyte (Phase II) Output: Concreting Slab on Grade, Installation of Trusses and Roof	0 linear meter PCCP, Existing Earth Road		54.86 cu.m of concreting of slab 448sq.m of Roof			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members


Prepared by:


NIKKI I. SERENO
PMC Secretariat

Approved:


HON. BENJAMIN A. TRAVERCO, JR.
PMC Chairperson

Noted by:


HON. ROLANDO M. VILLASENCIO
LCE