

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
KEY LESSONS LEARNED FROM ISSUES RESOLVED AND BEST PRACTICES
In 2026

Program/Project Title	Location	Implementing Agency	Problem/ Issue		Strategies/Actions Taken to Resolve the Problem/Issue	Responsible Entity/Key Actors and their Specific Assistance	Lessons learned and Good Practices that could be shared to the NPMC/Other PMCs
			Nature	Details			
Construction of Two Storey Multi-Purpose Hall, Brgy. Lunang II Almagro, Samar	Brgy. Lunang II	LGU Almagro	Design, Scope, Technical Specifications	Hairline cracks were observed on the rough finish wall	Recommend appropriate surface repair (like applying a suitable crack filler or patching compound on the gaps) and monitoring.	LPMC with the assistance of the Municipal Engineering Office	It is advisable to orient the LPMC members on the Detailed Engineering Design/Scope of Work of a certain project to make them aware before conducting an inspection.

Submitted by:	MERVYN O. DOCALLOS	Approved by:	HON. CANDIDO O. BONA, JR.
Designation/Office:	Almagro PMC Chairperson		Municipal Mayor
Date:	9-Jun-26	Date:	9-Jun-26