


REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
KEY LESSONS LEARNED FROM ISSUES RESOLVED AND BEST PRACTICES
In 2026

Program/Project Title	Location	Implementing Agency	Problem/ Issue		Strategies/Actions Taken to Resolve the Problem/Issue	Responsible Entity/Key Actors and their Specific Assistance	Lessons learned and Good Practices that could be shared to the NPMC/Other PMCs
			Nature	Details			
(a) Widening and Reconcreting of Existing Pavement at Pier 2, Poblacion 01	Poblacion 01	Municipality of Daram	Site Condition/Availability	Continuous rain induced for a series of month in 2025 thus caused the delay of project implementation	Fasttrack construction activities when the weather favors	Contractor	Regular monitoring of the project implementation
b. Installation of concrete pre-cast plank for road side protection and road embankment along Radial road at Poblacion 02	Pob01-Pob02	Municipality of Daram	Site Condition/Availability	Continuous rain induced for a series of month in 2025 thus caused the delay of project implementation	Fasttrack construction activities when the weather favors	Contractor	Regular monitoring of the project implementation
c. Construction of welcome Center at Pier 2 entrance	Poblacion 01	Municipality of Daram	Site Condition/Availability	Continuous rain induced for a series of month in 2025 thus caused the delay of project implementation	Fasttrack construction activities when the weather favors	Contractor	Regular monitoring of the project implementation
d. Improvement of Mayor Benito Park (Phase IV)	Pob 01	Municipality of Daram	Site Condition/Availability	Continuous rain induced for a series of month in 2025 thus caused the delay of project implementation	Fasttrack construction activities when the weather favors	Contractor	Regular monitoring of the project implementation
Concreting of one lane road portion of Birawan -Astorga Road at (sta. 12+000 to sta. 12+300)	Biran-Astorga Section	Municipality of Daram	Site Condition/Availability	Continuous rain induced for a series of month in 2025 thus caused the delay of project implementation	Fasttrack construction activities when the weather favors	Contractor	Regular monitoring of the project implementation
f. Construction of Multi-Purpose Building Phase I (Cost sharing) Pob. 02	Poblacion 02	Municipality of Daram	Site Condition/Availability	Continuous rain induced for a series of month in 2025 thus caused the delay of project implementation	Fasttrack construction activities when the weather favors	Contractor	Regular monitoring of the project implementation

--	--	--	--	--	--	--

			
Submitted by:	ARNEL REAL	Approved by:	LUCIA LATORRE-ASTORGA
Designation/Office:	LPMC Chairman		Municipal Mayor
Date:	12-Mar-26	Date:	Mar/12/2026