


**REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)**  
**PROBLEM SOLVING SESSIONS/FACILITATION MEETING CONDUCTED**  
**As of March 2026 (1st Quarter)**

| Program/Project Title                                             | Issue Details                                                                                                                                               | Issue Typology                                                      | Location                           | IA             | Date of Meeting   | Concerned Agencies | Agreements Reached                                                                                                                                                                                            |
|-------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|------------------------------------|----------------|-------------------|--------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Rehabilitation/ Repair of Local Access Road                       | - During inspection it has been found that NO project billboard installed at the site<br><br>-Excessive brooming has also been observed on the road surface | Performance of Contractors/Consultants                              | Avelino Street in Barangay Viejo   | LGU-Pagsanghan | February 23, 2026 | LGU-Pagsanghan     | The contractor agreed to install the required project billboard immediately and to undertake corrective measures on the road surface with excessive brooming to ensure compliance with project specifications |
| Rehabilitation/Repair of Local Access Road                        | - During inspection it has been found that NO project billboard installed at the site                                                                       | Performance of Contractors/Consultants                              | Repol Avenue in Barangay Canlapwas | LGU-Pagsanghan | February 23, 2026 | LGU-Pagsanghan     | The contractor agreed to immediately install the required project billboard at the site in compliance with project specifications.                                                                            |
| Construction of Multi-purpose Building (Child Development Center) | - Unreadable reference plan                                                                                                                                 | Capacity of Project Management Unit and Other Implementing Partners | Brgy. Bangon                       | LGU-Pagsanghan | February 23, 2026 | LGU-Pagsanghan     | The contractor agreed to provide a clear and readable copy of the reference plan for proper verification and record purposes                                                                                  |

|  |                                                                                                                                                                     |                                        |  |  |  |  |                                                                                                                                      |
|--|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|--|--|--|--|--------------------------------------------------------------------------------------------------------------------------------------|
|  | - Lateral ties were improperly installed.<br><br>-The hooks did not meet the required 135° bend, which does not comply with standard structural detailing practices | Performance of Contractors/Consultants |  |  |  |  | The contractor agreed to correct the hooks to meet the required 135° bend in accordance with standard structural detailing practices |
|--|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|--|--|--|--|--------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                   |                            |  |  |                                                                                     |                         |  |  |
|-----------------------------------------------------------------------------------|----------------------------|--|--|-------------------------------------------------------------------------------------|-------------------------|--|--|
|  |                            |  |  |  |                         |  |  |
| Submitted by:                                                                     | HON. HERBERT U. TARRAYO    |  |  | Approved by:                                                                        | HON. SED HENDRIX C. TAN |  |  |
| Designation/Office:                                                               | Pagsanghan PMC Chairperson |  |  |                                                                                     | Municipal Mayor         |  |  |
| Date:                                                                             | March 12, 2026             |  |  | Date:                                                                               | March 12, 2026          |  |  |