

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
KEY LESSONS LEARNED FROM ISSUES RESOLVED AND BEST PRACTICES
In 2026

Program/Project Title	Location	Implementing Agency	Problem/ Issue		Strategies/Actions Taken to Resolve the Problem/Issue	Responsible Entity/Key Actors and their Specific Assistance	Lessons learned and Good Practices that could be shared to the NPMC/Other PMCs
			Nature	Details			
CONSTRUCTION OF SCHOOL BUILDING	BRGY. NAPURO 1	LGU	LOW CEILING, INCOMPLETE ROOF CROSS BRACING, PWD RAMP NOT IN CONFORMITY WITH BP 344, REBARS NOT PROPERLY ANCHORED TO TRUSSES, TRUSSES JOINTS NOT FULLY WELDED, TRUSSES NOT FULLY PAINTED	Performance of Contractors/Consultants	PROVIDE PUNCH LIST TO CONTRACTOR ENUMERATING ALL DEFICIENCIES	LPMC SECRETARIAT	N/A
IMPROVEMENT OF LEVEL 2 WATER SUPPLY SYSTEM	BRGY. NAPURO 2	LGU	NO PROBLEM/ISSUE IDENTIFIED				

Submitted by:	 GEORGE BINAS	Approved by:	 HON. FELIX R. PANGARORON
Designation/Office:	SANTA MARGARITA-RMC Chairperson		Municipal Mayor
Date:	September 14, 2026	Date:	September 14, 2026