


LOCAL PROJECT MONITORING AND EVALUATION SYSTEM (LPMES)
 PROJECT INSPECTION REPORT
 As of June, 2026 (2nd Quarter)

Program / Project Title	Total Program/ Project Cost (PHP)	Location	IA	Date of Project Inspection	Details on Site(s) Inspected	Findings	Issues	Actions Taken	Actions to be Taken
Additional water source system at Sitio Kauswagan, Brgy. Himay-angan, Liloan So. Leyte (Water Drilling System)	854,061.92	Sitio Kauswagan, Brgy. Himay-angan, Liloan So. Leyte	Municipality of Liloan, So. Leyte	8-Jun-26	Upon inspection, project is completed.	None	None	None	None
Fabrication and Installation of Road Signs	288,944.30	Poblacion, Liloan So. Leyte	Municipality of Liloan, So. Leyte	8-Jun-26	Upon inspection, project is completed. Some signages are incorrect in placement or facing the wrong direction.	Some signages are incorrect in placement	Lacking in communication of proper placement of signage	The LPMC conducted a feedbacking meeting right after the project inspection.	Demand Contractor to properly place the incorrect signage

Prepared by:


 RENCIEL S. MERCADO
 Administrative Aide I/ LPMC Secretariat

Reviewed by:


 HERMINIA C. CERDEÑA
 MPDC/ LPMC Head Secretariat

Approved by:


 MANUEL B. URICO, JR.
 Lnb Pres. / LPMC Chairman


 JONNA C. ADAN
 Local Chief Executive