

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
PROJECT INSPECTION REPORT
As of March 25, 2026 (1st Quarter)

Name of Project (Total Project Cost)	Location	Implementing Agency	Date of Project Inspection	Major Findings	Issues	Action Taken/ Recommendation
CONCRETING OF PINTUYAN BOULEVARD Php. 7,000,000.00	Brgy. Pob. Ubos, Pintuyan, Southern Leyte	LGU- Pintuyan	3/24/2026		1. Project billboard not visible at site 2. No PPE for workers 3. Poor housekeeping at site	We recommend to inform the contractor to maintain cleanliness at work site, observe proper and consistent use of PPE during active work hours and re-install the project billboard
CONSTRUCTION OF PINTUYAN INTEGRATED TRANSPORT TERMINAL (PHASE I) Php. 5,500,000.00	Brgy. Ponod, Pintuyan, Southern Leyte	LGU- Pintuyan	3/24/2026		1. Project billboard not visible at site 2. No PPE for workers 3. Poor housekeeping at site	We recommend to inform the contractor to maintain cleanliness at work site, observe proper and consistent use of PPE during active work hours and re-install the project billboard

Submitted by : LOLITO B. ABOY
 Designation/ Office : MPDC- Designate/ PMC Secretariat
 Date : 25-Mar-26

Noted by: HON. RICARTE A. ESTRELLA
 Municipal Mayor

Note: This is a new form based on the existing RPMES forms. Adopted in 2015.