





REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
KEY LESSONS LEARNED FROM ISSUES RESOLVED AND BEST PRACTICES
In 2026

RPMES FORM 11

Program/Project Title	Location	Implementing Agency	Problem/ Issue		Strategies/Actions Taken to Resolve the Problem/Issue	Responsible Entity/Key Actors and their Specific Assistance	Lessons learned and Good Practices that could be shared to the NPMC/Other PMCs
			Nature	Details			
Concreting of Local Access Road to Sanitary Land Fill	Brgy. Burabod, Macarthur, Leyte	LGU	Others	- Minimal hairline cracks detected in isolated sections. - Shoulders in some areas are loosely compacted. - No visible or insufficiently provided weakened plane (control) joints along certain stretches of the concrete pavement.	- The Municipal Engineering Office to cause the contractor to comply and rectify the noted findings identified during the project inspection. The project is still covered under 1 year defect and liability period.	LPMC/MEO	The implementation of the Concreting of Local Access Road to Sanitary Landfill demonstrated that early stakeholder engagement, strict quality monitoring, proper documentation, and integration of sustainability measures are key to achieving efficient, transparent, and durable local infrastructure projects.

Submitted by:	 EnP Joel L. Villacorte	Approved by:	 Hon. Jonathan T. Barquin	Noted by:	 Hon. Rudin Y. Babante
Designation/Office:	LPMC Secretariat		LPMC Chairman		Municipal Mayor
Date:	March 18, 2026	Date:	March 18, 2026	Date:	March 18, 2026