

**LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
For CY 2026**

PMC: Palompon, Leyte

Description of Indicators	Baseline Data (Y0)	Target Values (2026)				Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/ Person Responsible to Collect	Unit/ Person Responsible to Report
		1st Quarter	2nd Quarter	3rd Quarter	4th Quarter					
Output per project: Title: Concreting of Farm to Market Road- Liberty-Mabini Road Output: 58m with 1m shouldering both sides	No existing concrete road prior to the project.		The road concreting works covering 58 meters, with 1-meter shoulder on both sides.			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Concreting of Farm to Market Road- Liberty-Mabini Road Output: 58m with 1m shouldering both sides	No existing concrete road prior to the project.		The road concreting works covering 58 meters, with 1-meter shoulder on both sides.			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Concreting of Farm to Market Road- Brgy. Cangmoya Road Output: 58m with 1m shouldering both sides	No existing concrete road prior to the project.		The road concreting works covering 58 meters, with 1-meter shoulder on both sides.			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Concreting of Farm to Market Road- Caminoy-San Pedro Road Output: 58m with 1m shouldering both sides	No existing concrete road prior to the project.		The road concreting works covering 58 meters, with 1-meter shoulder on both sides.			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Concreting of Farm to Market Road- Brgy. San Guillermo Road Output: 58m with 1m shouldering both sides	No existing concrete road prior to the project.		The road concreting works covering 58 meters, with 1-meter shoulder on both sides.			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members
Output per project: Title: Concreting of Farm to Market Road- Masaba Road Output: 58m with 1m shouldering both sides	No existing concrete road prior to the project.		The road concreting works covering 58 meters, with 1-meter shoulder on both sides.			Inspection Report (SWA) of MEO/ PIT	Review of Documents, Site Inspection	Quarterly	LPMC Secretariat	LPMC Chairman and Members

Prepared by:

Mr. Noel P. Sanchez
MPDC/Secretary LPMC

Approved:

Mr. Christopher T. Montebon
Chairperson, LPMC

Noted by:

Mary Dominante A. Ofiate
LGE