

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMS)
KEY LESSONS LEARNED FROM ISSUES RESOLVED AND BEST PRACTICES
 June 2026 (2nd Quarter)

Program/Project Title	Location	Implementing Agency	Problem Issues Nature	Details	Strategies/Actions Taken to Resolve the Problem/Issue	Responsible Entity/Key Actors and their Specific Assistance	Lessons learned and Good Practices that could be shared to the NPMC/Other PMCs
CONSTRUCTION OF ONE STOREY TWO CLASSROOM SCHOOL BUILDING AT BRGY. GIBATANGAN, LAOANG, NORTHERN SAMAR	BRGY. GIBATANGAN, LAOANG, NORTHERN SAMAR	LGU Laong	Contractors' performance in project implementation	Incomplete installation of glaze and unglaze tiles, lacking 1 unit of 1000L Stainless Water Tank, incomplete provision of safety hand rail for PWD Toilet	Coordinated with the concerned contractor and MEO assigned personnel to submit as-built drawings in compliance of actual work done	LPMC, MEO, Contractor	To ensure and verified if the projects are in accordance with appropriate specifications and approved technical plans

Prepared:

Jhivert
ENP. JESSON T. RIVERA
 Secretariat

Dennis L. Pedimonte
DENNIS L. PEDIMONTE
 Secretariat

Engr. Rochel I. Nebrida
Engr. ROCHEL I. NEBRIDA
 Secretariat

Recommending Approval:

Salvador P. Acebuche
SALVADOR P. ACEBUCHE
 LPMC Chairperson

Approved:

Hon. Charlene L. Ongchuan
HON. CHARLENE L. ONGCHUAN
 Local Chief Executive

Date: June 30, 2026