


REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMS)
 PROJECT INSPECTION REPORT
 As of 2nd Quarter 2026

Program/Project Title	Total Program/Project Cost (PHP)	Location	IA	Date of Project Inspection	Details on Site(s) Inspected	Findings	Issues	Actions Taken	Actions to be Taken
CONSTRUCTION OF ONE (1) UNIT CLASSROOM BUILDING	2,494,543.47	REHABILITATION OF WATER SYSTEM	BARANGAY BAYHO			1. UNPROPERLY MAINTAINED EXISTING INTAKE BOX; 2. EXPOSED OR BURIED PIPELINES 3. OPEN AND OR NOT WATER TIGHT STRUCTURE 4. USING PIPE ON SOME TAP STAND USING IMPROVISED RUBBER TO STEAL PIPE LINE LEAK 5. INSTALLATION OF PIPELINES ON DRAINAGE SYSTEM	UNCLEANED INTAKE BOX	BLGU TO PROPERLY MAINTAIN EXISTING BOX QUARTERLY TO AVOID CONTAMINATION 2. BURY ALL EXPOSED PIPELINES 3. CONSTRUCT WINGWALL ON WATER SOURCE TO PREVENT DIVERSION OF SPRING WATER FLOW AND INSTALL NET TO AVOID WATER CONTAMINATION . 4. REMOVE AND RELOCATE	N/A
CONSTRUCTION OF FARM MARKET ROAD (RE-VISIT)	3,994,861.33	IMPROVEMENT OF WATER SYSTEM	BARANGAY CURRY			1.OPEN AND OR WATER TIGHT STRUCTURE AND PRONE CONTAMINATION 2. EXPOSED / UNBURRIED PIPELINES 3. CONSTRUCTED INTAKE OR COLLECTION BOX NOT PROPERLY MAINTANED	N/A	CLEAN AND INSTALL NET /COVER THE WATER TO PREVENT CONTAMINATION 2. BURY ALL EXPOSED 3. CONDUCTED FACILITY SHOULD BE PROPERLY MAINTAINED QUARTERLY TO AVOID CONTAMINATION	N/A
CONSTRUCTION OF FARM RO MARKET ROAD	1,995, 425.37	CANAL CONCRETING WITH COVER	BARANGAY SAN MIGUEL			1. DRAINAGE CANAL - TOTALLY COVERED WITH CONCRETE EXTENSION OF PATHWAY LENGTH 64.7 METERS WIDTH 1 METER THICKNESS 150 MM 2, WITH 7 METERS CONCRETE EXTENSION TO EVACUATION CENTER . 3. PROJECT COMPLETED	N/A	N/A	N/A

Submitted by:		Approved by:	
Designation/Office:	MICAEL ALMENDO LPMC CHAIRMAN		BOBBY C. SALUDARIO MUNICIPAL MAYOR
Date:	06/05/2026	Date:	06/05/2026