


REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
KEY LESSONS LEARNED FROM ISSUES RESOLVED AND BEST PRACTICES
in CY 2026
As of September 2026 (Quarterly)

Program/Project Title	Location	Implementing Agency	Problem/ Issue		Strategies/Actions Taken to Resolve the Problem/Issue	Responsible Entity/Key Actors and their Specific Assistance	Lessons learned and Good Practices that could be shared to the NPMC/Other PMCs
			Nature	Details			
Construction of Covered Court @ So. Canunay, Brgy. Rosal	So. Canunay, Brgy. Rosal	Municipality of Sta. Rita	Others	none	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Construction of Multi-Purpose Hall @ Brgy. Bokinggan	Brgy. Bokinggan	Municipality of Sta. Rita	Others	none	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Construction of Health Center @ Brgy. Cabunga-an	Brgy. Cabunga-an	Municipality of Sta. Rita	Others	handling of materials	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Construction of Health Center @ Brgy. Igang-Igang	Brgy. Igang-Igang	Municipality of Sta. Rita	Others	handling of materials	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Construction of Multi-Purpose Hall / Day Care Center @ So. Tomandog, Brgy. Salvacion	So. Tomandog, Brgy. Salvacion	Municipality of Sta. Rita	Others	none	Monitored and inspected	LGU, BLGU, CSO, Contractor	Providing a summary of findings to the contractor to streamline project works.
Construction of Multi-Purpose Hall / Day Care Center @ Brgy. Binanalan	Brgy. Binanalan	Municipality of Sta. Rita	Others	none	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Construction of Multi-Purpose Hall @ Brgy. San Juan	Brgy. San Juan	Municipality of Sta. Rita	Others	none	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Construction of Multi-Purpose Hall @ Brgy. San Pascual	Brgy. San Pascual	Municipality of Sta. Rita	Others	delivery of roofing materials	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Construction of Multi-Purpose Hall @ Brgy. Union	Brgy. Union	Municipality of Sta. Rita	Others	none	Monitored and inspected	LGU, BLGU, CSO, Contractor	Effective communication with the contractor to fastrack project construction
Continuation of Bridge/ Wharf @ Brgy. Tagacay	Brgy. Tagacay	Municipality of Sta. Rita	Others	handling of materials	Monitored and inspected	LGU, BLGU, CSO, Contractor	Requiring "Before, During, and After" photos from the same GPS coordinates. This provides an indisputable "Timeline of Progress" for the LPMC and oversight agencies.

Submitted by:	 ENGR. RUEL T. DUALLO, ENP	Approved by:	 HON. JASCHA MAE R. TIW
Designation/Office:	MPDC		Municipal Mayor
Date:		Date:	