


LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
For CY 2026-2030


PMC: VILLAREAL PROJECT MONITORING COMMITTEE

PROJECT NAME	Description of Indicators	Baseline Data (2025)	Target Values (3-5 Years)					Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/ Person Responsible to Collect	Unit/ Person Responsible to Report
			Y1 (2025)	Y2 (2026)	Y3 (2027)	Y4 (2028)	Y5 (2029)					
1. CONSTRUCTION OF MULTI PURPOSE HALL AT BRGY MAHAYAG, VILLAREAL, SAMAR	1,474 no of population have access to multi purpose hall	absence of multi purpose hall	1 building constructed	functional multi purpose hall	functional multi purpose hall	functional multi purpose hall	functional multi purpose hall	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
2. INSTALLATION OF INTEGRATED SOLAR STREET LIGHT AT BRGY MIRAMAR, VILLAREAL, SAMAR	326 no of population have access to solar street light	presence of darkness in some areas	73 set of solar installed	safe and secured area	safe and secured area	safe and secured area	safe and secured area	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
3. CONSTRUCTION OF DRAINAGE CANAL AT SITIO LUSONG, BRGY CANMUCAT, VILLAREAL, SAMAR	1708 no of population had access to drainage canal constructed	prone to flooding	safe and secured community	safe and secured community	safe and secured community	safe and secured community	safe and secured community	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
4. INSTALLATION OF SOLAR STREET LIGHT AT BRGY MERCADO, VILLAREAL, SAMAR	265 no of population have access to solar street light	presence of darkness in some areas	installed and functional solar street light	safe and secured area	safe and secured area	safe and secured area	safe and secured area	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
5. REPAIR OF MULTI PURPOSE HALL AT BRGY SAN ANDRES, VILLAREAL, SAMAR	1,554 no of population had access to multi purpose hall	poor multi purpose hall	1 building repaired and improved	functional multi purpose hall	functional multi purpose hall	functional multi purpose hall	functional multi purpose hall	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
6. INSTALLATION OF INTEGRATED SOLAR STREET LIGHT AT BRGY CENTRAL, VILLAREAL, SAMAR	206 no of population have access to solar street light	presence of darkness in some areas	installed and functional solar street light	safe and secured area	safe and secured area	safe and secured area	safe and secured area	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
7. INSTALLATION OF INTEGRATED SOLAR STREET LIGHT AT BRGY STO NINO, VILLAREAL, SAMAR	758 no of population have access to solar street light	presence of darkness in some areas	installed and functional solar street light	safe and secured area	safe and secured area	safe and secured area	safe and secured area	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
8. CONSTRUCTION OF CIVIC CENTER AT BRGY VILLAROSA, VILLAREAL, SAMAR	914 no of population had access to civic center	absence of civic center	1 building constructed with an area of 375 square meter	functional civic center	functional civic center	functional civic center	functional civic center	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN
9. INSTALLATION OF INTEGRATED SOLAR STREET LIGHT AT BRGY TAYUD, VILLAREAL, SAMAR	326 no of population have access to solar street light	presence of darkness in some areas	installed and functional solar street light	safe and secured area	safe and secured area	safe and secured area	safe and secured area	MPDC.MEO	SITE INSPECTION, SWA	MONTHLY/ QUARTERLY	MEO/PMC	PMC CHAIRMAN


Prepared by:


MAES. ORTIZ
PMC Secretariat

Approved:


MARLYN E. MATIAS
PMC Chairperson

Noted by:


MARILOU R. LATORRE
LCE