

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMS)
PROJECT INSPECTION REPORT
As of [Month] [Year] (Quarterly)

Program/Project Title	Total Program/Project Cost (PHP)	Location	IA	Date of Project Inspection	Details on Site(s) Inspected	Findings	Issues	Actions Taken	Actions to be Taken
DESIGN AND BUILD REHABILITATION OF THE WATER SYSTEM PROJECT/IMPROVEMENT OF WATER MAINLINE PIPES	23,092,409.72	San Juan-Sto. Rosario	Municipal	18-Sep-26	Billboard not on DILD format	Billboard not on DILD format	Billboard not on DILD format	Informed the contractor	verbal instruction to contractors field engineer.
Improvement of Public Plaza Phase I	1,698,234.04	Poblacion	Municipal	19-Sep-26	completed	waste materials exist.	waste materials exist.	Informed the contractor	verbal instruction to contractors field engineer.
Improvement of Public Plaza Phase II	1,619,059.04	Poblacion	Municipal	20-Sep-26	on progress				
Improvement of Municipal hall	870,584.25	Poblacion	Municipal	21-Sep-26	on progress				
Construction of Stock Room and garrage Phase III	852,920.27	Poblacion	Municipal	22-Sep-26	on progress				
Construction of Port Commercial Building	978,992.36	Poblacion	Municipal	23-Sep-26	on progress				
Construction of one storey Stall For Fish brokers Phase I	1,098,930.95	Sta. Sofia	Municipal	24-Sep-26	on progress				
Construction of Portland Cement Concrete Pavement	998,486.70	Sta. Sofia	Municipal	25-Sep-26	completed	no construction joint	no construction joint	Informed the contractor	verbal instruction to contractors field engineer.
Backfilling and Concrete paving of Existing Seawall	1,998,241.74	Cantutang	Municipal	26-Sep-26	completed				

Submitted by:	 ENGR. EMMANUEL E. GULAY EnP	Approved by:	 MARIA FE CRISPINA B. POBLETE
Designation/Office:	MPDC		MUNICIPAL MAYOR
Date:	25-Sep-26	Date:	25-Sep-26