

**PROVINCIAL PROJECT MONITORING COMMITTEE (PPMC)
MONITORING AND EVALUATION PLAN
For CY 2026**

PPMC: Province of Leyte

Description of Indicators	Baseline Data (Y0)	Target Values (2026)				Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/ Person Responsible to Collect	Unit/ Person Responsible to Report
		1st Quarter	2nd Quarter	3rd Quarter	4th Quarter					
Rehabilitation and Improvement and Road from Junction National Road to Busay Falls Entrance in Babatngon, Leyte						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
Construction of a Three (3) Storey Multi-Purpose Building in Brgy, Cavite West, Palo, Leyte						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
FY 2026 FALGU Assistance to individuals or families – food assistance/rice distribution project						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
FY 2026 FALGU Assistance to individuals or families – food assistance/rice distribution project						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
FY 2025 Green Green Program						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
Rehabilitation and Improvement of Provincial Road in Barangay Baculanad, Capoocan, Leyte						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
Construction of Multi-Purpose Building in Brgy. Abaca, Dagami, Leyte						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
Construction of Multi-Purpose Building in Brgy. Sampaguita, Dagami, Leyte						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
Rehabilitation of Multi-Purpose Building in Brgy. Libertad, Capoocan, Leyte						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members
Construction of Seawall in Brgy. Cabul-an, Capoocan, Leyte						Inspection Report (SWA) of PEO/ PIT	Review of Documents, Site Inspection	Quarterly	PPMC Secretariat	PPMC Chairman and Members

Prepared by:

^ .



Approved/Noted by:



AGNES C. RAFON
PPMC Secretariat



LOVELL ANNE M. YU-CASTRO
PPMC Chairman



CARLOS JERICO L. PETILLA
Governor