

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
PROJECT INSPECTION REPORT
as of 1st Quarter of 2026

PMC: MUNICIPALITY OF BILIRAN

Name of Project/ Program Components	Location	Implementing Agency	Date of Project Inspection	Major Findings	Issues	Action Taken/ Recommendations
Construction of Man-made Falls to Swimming Pool	San Roque	LGU Biliran	March 9, 2026	Ensure all workers maintain consistent PPE compliance , implement daily site clean up protocols, install safety signage throughout the site	negative slippage	Together with MEO, closely coordinate and assist the contractor to fast-track construction activities and meet project timelines
Construction of Swimming Pool & Cabanas	San Roque	LGU Biliran	March 9, 2026		negative slippage	
Construction of Boardwalk & Nipa Huts in Eco Park	San Roque	LGU Biliran	March 9, 2026	Undisposed construction debris remains on-site	negative slippage	Immediate corrective action is recommended to remove and properly dispose of all construction debris, with strict compliance to environmental standards
Construction of Slope Protection at Hostel Building	San Roque	LGU Biliran	March 9, 2026	Ensure all workers maintain consistent PPE compliance , implement daily site clean up protocols, install safety signage throughout the site	negative slippage	Together with MEO, closely coordinate and assist the contractor to fast-track construction activities and meet project timelines
Hostel Interior Design, Furniure, Equipment, & Other Facilities	San Roque	LGU Biliran	March 9, 2026		negative slippage	

Submitted by:
Designation/ Office:
Date:

HON. MARIO A. NIERRAS
LPMC Chairperson
March 9, 2026

Noted by: GRACE J. CASIL
Agency Head

Note: This is a new form based on the existing RPME forms Adopted in 2015.