

REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
PROJECT INSPECTION REPORT
As of September 2026 (3rd Quarter)

PMC: _____

Name of Project/ Program Components	Location	Implementing Agency	Date of Project Inspection	Major Findings	Issues	Action Taken/ Recommendations
FMR Sitio Banawag	Brgy. Langit, Alangalang, Leyte	LGU-MEO	15-Sep-26	Lack of Road Shouldering	The road requires proper shouldering to provide adequate support to the pavement edges, improve road safety, and prevent further deterioration of the roadway	Consult the Contractor
Road Development and Car Park at Community College	Bgry. Salvacion Pob. Alangalang, Leyte	LGU-MEO	15-Sep-26	Lack of Road Shouldering	The road requires proper shouldering to provide adequate support to the pavement edges, improve road safety, and prevent further deterioration of the roadway	Consult the Contractor
Construction of General Services Office Building	Brgy. Hubang Alangalang, Leyte	LGU-MEO	15-Sep-26	Poor Quality of Materials Used for the Storage Door	The materials used for the storage door were observed to be of poor quality and may not meet the required specifications and standards.	Consult the Contractor
Rehabilitation of Multi-Purpose Building in Alangalang, Leyte	LGU Compound	LGU-MEO	15-Sep-26	Non-Compliance with PPE Requirements	Workers at the construction site were observed not fully complying with the required use of Personal Protective Equipment (PPE)	Consult the Contractor

Submitted by:
Designation/ Office:
Date:

ELMER D. MATOBATO

SB Member MC Chairman

Sept. 2025

Noted:

HON. LOVELL ANNE M. YU-CASTRO

Mun. Mayor

Note: This is a new form based on the existing RPMES forms Adopted in 2015.

Distance 1.0



REGIONAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMES)
 PROJECT INSPECTION REPORT
 As of Month Year (Quarterly)

Name of Project (Total Project Cost)	Location	Implementing Agency	Date of Project Inspection	Major Findings	Issues	Action Taken / Recommendation
---	----------	------------------------	-------------------------------	----------------	--------	----------------------------------

RPMES REPORTS

OUTPUT FORMS

Form	Description
Project Inspection Report (RPMES Form No. 7)	This report shall provide the highlights of the project inspection, validation of the actual accomplishments provided in progress reports, and discussion of relevant issues encountered during the inspection.