

MUNICIPAL PROJECT MONITORING AND EVALUATION SYSTEM (RPMS)
PROJECT INSPECTION REPORT
April-June 2026

Program/Project Title	Total Program/Project Cost (PHP)	Location	IA	Date of Project Inspection	Details on Site(s) Inspected	Findings	Issues	Actions Taken	Actions to be Taken
Concreting of Barangay Road	996,764.96	Brgy. Mabini, Bato, Leyte	LGU-Bato Leyte	June 19, 2026	Exact Location of Completed Project	Completed	NONE	NA	NA
Construction of Concrete Pedestal and Installation of Solar Lights	496,821.18	Brgy. Cebuana, Bato, Leyte	LGU-Bato Leyte	June 19, 2026	Exact Location of Completed Project	Completed	NONE	NA	NA
Construction of Elevated Tank (Water System Level I)	493,586.75	Brgy. Cebuana, Bato, Leyte	LGU-Bato Leyte	June 19, 2026	Exact Location of Completed Project	Completed	NONE	NA	NA

Submitted by:	 ENGR. RIZALINA M. BUZON	Approved by:	 MARISSA C. GERTOS
Designation/Office:	MPDC/Secretary LPMC		Chairperson, LPMC
Date:	June 19, 2026	Date:	June 19, 2026