

PROJECT INSPECTION REPORT

Project : Concreting of Barangay Road
Project Cost : P996,764.96
Location : Brgy. Mabini, Bato, Leyte
Date of Inspection : June 19, 2026



PROJECT INSPECTION REPORT

Project : Construction of Concrete Pedestal and Installation of Solar Lights
Project Cost : P496,821.18
Location : Brgy. Cebuana, Bato, Leyte
Date of Inspection : June 19, 2026





PROJECT INSPECTION REPORT

Project : Construction of Elevated Tank (Water System Level I)
Project Cost : P493,586.75
Location : Brgy. Cebuana, Bato, Leyte
Date of Inspection : June 19, 2026



