



MUNICIPALITY OF CAPOOCAN, LEYTE

POST ACTIVITY REPORT

ACTIVITY:	Local Project Monitoring Committee (LPMC) 3rd Quarter Meeting & On-site Inspection of the Projects.
DATE:	September 24, 2026
VENUE:	BAC Office
PARTICIPANTS:	LPMC Members, LPMC Secretariat, Engineers & Engineering Staff

REPORT SUMMARY

I. OBJECTIVES OF THE ACTIVITY:

- Aimed to strengthen the capacities and enhance the knowledge of member of the Local Project Monitoring Committee (LPMC) on the different aspects of project monitoring and project implementation relevant to their roles and responsibilities.

II. HIGHLIGHT/S OF THE ACTIVITY:

- Conducted site inspection & monitoring of Subgrade and Based Course Preparation of Access Road Leading to Slaughterhouse, Road surfacing in the Tide Embankment Project (Poblacion Zone II) and Construction of Mini-Museum and Gallery.

III. OUTPUT/S OF THE ACTIVITY:

- Approved LPMC Resolutions.

IV. RECOMMENDATIONS/RELEVANT APPLICATION (if any):

- It is recommended to provide the list and schedule of all projects to be monitored.

V. REQUESTED ACTIONS (if any):

- N/A

VI. FUNDING SOURCE AND BUDGET

LGU General Fund: Special Bodies – Other MOOE = Php 4,500.00

Prepared by:

KIMBERLY N. GONZAGA
AA-II

Approved by:

BENITO C. PROCIA
MPDC



MUNICIPALITY OF CAPOOCAN, LEYTE
POST ACTIVITY REPORT

PHOTO DOCUMENTATION: Capoocan LPMC On-Site Inspection of Ongoing Projects

Opening and Concreting of Road at Brgy. Manloy





MUNICIPALITY OF CAPOOCAN, LEYTE

POST ACTIVITY REPORT

PHOTO DOCUMENTATION: Capoocan LPMC On-Site Inspection of Ongoing Projects

Installation of Solar Streetlights at Capoocan Village (Brgy. Balucanad & Brgy. Balud)





MUNICIPALITY OF CAPOOCAN, LEYTE

POST ACTIVITY REPORT

PHOTO DOCUMENTATION: Capoocan LPMC On-Site Inspection of Ongoing Projects

Construction of Mini-Museum and Gallery

