

**LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
For CY 2026**

PMC: **LGU-Palo**

No.	Description of Indicators	Baseline Data (Y0)	Target Values (2025)				Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/Person Responsible to Collect	Unit/Person Responsible to Report
			1st Quarter	2nd Quarter	3rd Quarter	4th Quarter					
1	Construction of Multi-Purpose Building in Brgy. San Jose, Palo, Leyte	0					Inspection Progress Report of Engineer's Office	Review of Documents; Ocular Inspection	Quarterly	LPMC Secretariat	LPMC Chairperson
2	Improvement of Day Care Center in Brgy. San Agustin, Palo, Leyte	0					Inspection Progress Report of Engineer's Office	Review of Documents; Ocular Inspection	Quarterly	LPMC Secretariat	LPMC Chairperson
3	Improvement of Day Care Center in Brgy. Teraza, Palo, Leyte	0					Inspection Progress Report of Engineer's Office	Review of Documents; Ocular Inspection	Quarterly	LPMC Secretariat	LPMC Chairperson

Prepared by:

ENGR. ARMAND C. CABALTERA
PMC Secretariat

Approved:

FELIPE T. YGRUBAY JR.
PMC Chairperson

Noted by:

REMEDIOS "MATIN" L. PETILLA
LCE