


LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
For CY 2026

PMC: TABANGO


Description of Indicators	Baseline Data (2025)	Target Values (2026)				Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/ Person Responsible to Collect	Unit/ Person Responsible to Report
		1st Quarter	2nd Quarter	3rd Quarter	4th Quarter					
Construction of New Commercial Building (Tenement B), Poblacion, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Road Reblocking @ Brgy Campokpok, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Road Reblocking @ Brgy Catmon, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Construction of Drainage Canal (Phase 2), Sitio Sabang Brgy Campokpok, Tabango, Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Construction of Footbridge (Phase 2), Sitio Sanagay, Brgy Gimarco, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Construction of Footbridge, Sitio Oboob 1, Brgy Campokpok, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Road Reblocking @ Sitio Libongaoging to Sitio burabod - Veloso Brgy Inangatan,, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Construction of Drainage Canal (Phase 3), @ Mabini St. Brgy Poblacion Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Road Concreting @ Sitio Calumbangan, Brgy Catmon, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Construction of Multi Pupose Facility/Covered Courtt (Phase 2) Sitio Masisi, Brgy Poblacion Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Road Concreting @ Proper Butason I, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Construction of Multi Pupose Facility/Covered Coiurt (Phase 2) 1st Avenue Brgy Poblacion Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Construction of Multi Pupose Facility/Covered Coiurt (Phase 5) Proper Brgy Gibacungan, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson
Road Concreting @Brgy Gimarco, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LPMC Secretariat	LPMC Chairperson

Road Concreting @ Sitio Tahad, Brgy Campokpok, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LMPC Secretariat	LMPC Chairperson
Rehabilitation Improvement of Kindergarten Classroom (Phase 2) SitioKawayan, Brgy Sta Rosa, Tabango Leyte						Site Inspection Report from MEO	Review of Documents	Quarterly	LMPC Secretariat	LMPC Chairperson

Prepared by:

ROGER DONSZON
 PMC Secretariat

Approved:

LOUINIE N. UY
 PMC Chairperson

Noted by:

MA CORAZON E. REMANDABAN
 LCE