




Republic of the Philippines
Province of Leyte
Municipality of Tanauan

LOCAL PROJECT MONITORING COMMITTEE

PHOTO DOCUMENTATION


Activity : Local Project Monitoring Committee (LPMC) 3rd Quarter On-Site Inspection

Date : September 17, 2026

Location : Four identified barangays (Brgy. San Roque, Brgy. Cabuynan, Brgy. Lapay, and Brgy. San Miguel)

**Project Title: Major Repair and Improvement of Various Sections of Public Market
Brgy. San Roque, Tanauan, Leyte**








**Project Title: Periphery Improvement and Security Enhancement of Sanitary Landfill
(Phase 1) Brgy. Cabuynan, Tanauan, Leyte**





Project Title: Safe Closure and Rehabilitation of Open Dumpsite, Brgy. Lapay, Tanauan, Leyte





Project Title: Construction of 68 units Perimeter Layer Niches, Brgy. San Miguel, Tanauan, Leyte



