



LOCAL PROJECT MONITORING COMMITTEE (LPMC)
MONITORING AND EVALUATION PLAN
For CY 2026

PMC: CAPUL, NORTHERN SAMAR, REGION VIII

Description of Indicators	Baseline Data (Y0)	Target Values (2026)				Sources of Data	Method of Data Collection	Timing/ Frequency	Unit/ Person Responsible to Collect	Unit/ Person Responsible to Report
		1st Quarter	2nd Quarter	3rd Quarter	4th Quarter					
Construction of Box Culvert and Reinforced Concrete Drainage Canal		100%	-	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Two-Storey Barangay Hall Extension with Day Care Center		100%	-	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Roads & Improvement of Structural Concrete Box Culvert		85%	15%	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Multi-Purpose Building		100%	-	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Multi-Purpose Building		100%	-	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Perimeter Fence		100%	-	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Perimeter Fence of Multi-Purpose Building		100%	-	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC

Prepared by:

ENGR. PETRONILO B. CABANG JR.
PMC Head Secretariat


Approved:

DANILO D. AMPUAN
PMC Chairperson


Noted by:

ISIDRO S. BANDAL
LCE

Construction/Improvement of CapulCircumferential Road						MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Multi-Purpose Building (Tourism Building Phase 1)						MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction/ Expansion of Water System		70%	30%	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction/ Expansion/ Improvement of Irrigation System		70%	30%	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Reinforced Concrete Drainage Canal		70%	30%	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Slope Protection & Reinforced Concrete Drainage Canal		60%	40%	-	-	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Road		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Improvement and Rehabilitation of Road		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Multi-Purpose Building		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Barangay Road		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Covered Walkway		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC

Construction of Cabin/Cottages		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Reinforced Concrete Drainage Canal, Barangay 1, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Reinforced Concrete Drainage Canal, Barangay 2, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Reinforced Concrete Drainage Canal, Barangay 1, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Improvement and Rehabilitation of Road, San Ignacio Street and Buenaventura Street, Barangay 2, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Road, From Barangay Oson to Barangay 1, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Barangay Road, Barangay Jubang, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Slope Protection, Barangay Sawang, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Construction of Multi-Purpose Building Phase II, Barangay Landusan, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC
Improvement of Barangay Road, Barangay San Luis, Capul Northern Samar		-	-	50%	50%	MEO	Document Review, Field Monitoring	Quarterly	MEO/LPMC	Engineer/MPDC

Prepared by:

ENGR. PETRONILO B. CABANG JR
 PMC Head Secretariat

Approved:

DANILO B. AMPUAN
 PMC Chairperson

Noted by:

ISIDRO S. BANDAL
 LCE