

CONSTRUCTION OF ONE-STOREY SCHOOL BUILDING AT BRGY. CAGDA-O



PHYSICAL STATUS : 100% COMPLETED

CONSTRUCTION OF ONE-STOREY SCHOOL BUILDING AT BRGY. CAMAYA-AN



PHYSICAL STATUS : 100% COMPLETED

CONSTRUCTION OF ONE-STOREY SCHOOL BUILDING AT BRGY. MONTALBAN




PHYSICAL STATUS : 100% COMPLETED

CONSTRUCTION OF HEALTH STATION AT BRGY. CAMANGGARAN



PHYSICAL STATUS : 100% COMPLETED

CONSTRUCTION OF HEALTH STATION AT BRGY. DEIT DE TURAG



PHYSICAL STATUS : **100% COMPLETED & TURNED-OVER**

CONSTRUCTION OF HEALTH STATION AT BRGY. GUSARAN



PHYSICAL STATUS : 100% COMPLETED

CONSTRUCTION OF HEALTH STATION AT BRGY. SAN ISIDRO



PHYSICAL STATUS : 100% COMPLETED